
COPPERWATCHER TIME WIRING FOR MULTIPLE PRESSURE SENSORS

MODEL # CW-3





AS SHOWN = 1K RESISTANCE

REVERSE P2 AND P3 = 0 K RESISTANCE

COPPERWATCHER TEM

PO BOX 210604 BEDFORD, TX 76095

PHONE: 817.684.1216

WWW.COPPERWATCHER.COM

LEGEND

DATE: 03/05/13

DRAWN BY: DRAWING #: V. KOLODETSKY